Message

From: Wayne Miller [Miller.Wayne@azdeq.gov]

Sent: 11/21/2016 11:02:53 PM

To: d'Almeida, Carolyn K. [dAlmeida.Carolyn@epa.gov]; Davis, Eva [Davis.Eva@epa.gov]

Subject: 2016-11-21 - WAFB - FYI - uxo report for Nov 21 ST012 - C24 and U38 wells in construction - SB17 converted to well

L55 - location move - sw uxo

Attachments: ST012 Well locations_CZ24_UWBZ38_LSZ55.docx

FYI -

From: Steve Willis [mailto:steve@uxopro.com] **Sent:** Monday, November 21, 2016 3:39 PM **To:** Wayne Miller <Miller.Wayne@azdeq.gov>

Subject: 2016-11-21 - WAFB - uxo report for Nov 21 ST012 - C24 and U38 wells in construciton - SB17 converted to well

L55 - location move - sw uxo

Wayne,

I did not go out to ST012 today, but called Tiana at AMEC to get an update. Both boreholes have been completed and well construction is proceeding. According to Tiana, neither boring showed any indications of hydrocarbon impact. CZ24/UWBZ38 are being constructed as proposed. Boring SB17 has been converted to well LSZ55. Due to conflicts with the proposed location of this boring, it was moved south and is in the center of the parking lot. Because it is now relatively close to CZ24/UWBZ38, they converted it to the well. Due to its proximity to the nested well, it doesn't look like they are going to drill another boring and or LSZ well in this area, although Tiana wasn't completely sure what the plan is. I attached a figure showing the approximate revised well location for LSZ55.

Steve Willis UXO Pro, Inc. steve@uxopro.com 480-316-3373

NOTICE: This e-mail (and any attachments) may contain PRIVILEGED OR CONFIDENTIAL information and is intended only for the use of the specific individual(s) to whom it is addressed. It may contain information that is privileged and confidential under state and federal law. This information may be used or disclosed only in accordance with law, and you may be subject to penalties under law for improper use or further disclosure of the information in this e-mail and its attachments. If you have received this e-mail in error, please immediately notify the person named above by reply e-mail, and then delete the original e-mail. Thank you.